SUPPLEMENTARY INFORMATION ON FUTURE MAJOR REPAIRS AND REPLACEMENTS JUNE 30, 2023 (UNAUDITED)

The following information on common area major components was compiled by Browning Reserve Group of Sacramento, California **as of March 2023** and has served as the basis for the current estimates of replacement reserve funding:

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2022/2023 Fully Funded Balance
00001 - Hacienda Interior				
03500 - Painting: Interior				
300 - Clubhouse 21,475 sf Hacienda (50%)	3,543	5	1	2,835
04000 - Structural Repairs				
912 - Doors Kitchen Sliding Door	7,560	20	12	3,024
916 - Doors 5 Sliding Doors	37,800	20	14	11,340
08000 - Rehab	2 704			4 000
110 - General 3,440 sf Pavilion	3,784	8	4	1,892
120 - General 1,360 sf Lounge & Bar	5,018	8	5	1,882
130 - General 1,276 sf Gym & Library	4,951	12	5	2,888
140 - General 1,390 sf Kitchen	7,367	5	3	2,947
150 - General 922 sf Offices & Lobby	1,549	5	5	258
154 - General 376 sf [3] Rental Offices	3,809	10	3	2,666
160 - General 649 sf Lower Apartment	4,115	8	3	2,572
162 - General 300 sf Lower Apartment- Patio Repair	1,065	10	3	746
170 - General 1,251 sf Upper Apartment	6,630	8	3	4,144
220 - Restrooms 2 Near Lounge	1,575	8	1	1,378
230 - Restrooms 2 Near Offices	1,575	8	5	591
14000 - Recreation				
290 - Exercise: Miscellaneous Equip. Multipurpose Room	16,234	15	15	1,015
22000 - Office Equipment				
200 - Computers, Misc. Office	6,740	15	15	421
23000 - Mechanical Equipment				
200 - HVAC Office	11,835	15	6	7,101
210 - HVAC 4 Pavilion Evaporative Units	13,241	15	3	10,592
220 - HVAC Lounge	4,301	30	6	3,441
260 - HVAC Lower Apartment	5,553	30	17	2,407
270 - HVAC Upper Apartment	8,414	30	20	2,805
630 - Water Heater Pavilion Restrooms	621	15	8	290
640 - Water Heater Kitchen	974	15	5	649
650 - Water Heater	974	15	1	909

SUPPLEMENTARY INFORMATION ON FUTURE MAJOR REPAIRS AND REPLACEMENTS JUNE 30, 2023 (UNAUDITED)

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2022/2023 Fully Funded Balance
00001 - Hacienda Interior				
23000 - Mechanical Equipment				
Pool Restrooms 660 - Water Heater	974	15	2	844
Lower Apartment	974	15	2	044
670 - Water Heater Upper Apartment	1,530	15	5	1,020
910 - Swamp Cooler Kitchen Evaporative Unit	1,982	30	6	1,586
24000 - Furnishings			_	
100 - Miscellaneous Office	4,520	10	3	3,164
104 - Miscellaneous Pavilion Stage	5,166	20	5	3,875
110 - Chairs 250 Pavilion Folding Chairs	9,360	25	1	8,986
114 - Chairs 40 Pavilion Folding Chairs	744	25	16	268
118 - Tables 75 Lounge Tables & Folding Chairs	6,829	25	14	3,005
160 - Miscellaneous Lower Apartment- 2019/2020	6,125	15	12	1,225
170 - Miscellaneous Upper Apartment Furnishings- 2019/2020	8,687	15	12	1,737
174 - Miscellaneous Upper Apartment Furnishings	2,227	15	3	1,782
400 - Sofa 3 Lower Apartment- Sofa/Loveseat/Table	1,304	15	12	261
24500 - Audio / Visual				
100 - Television Multipurpose Room	1,055	10	3	738
104 - Television Television- Lower Apartment	349	10	1	314
300 - PA System PA System	874	10	3	612
25000 - Flooring				
250 - Laminate 168 Sq. Yds. Offices & Reception Area	2,500	20	20	119
260 - Laminate 73 Sq. Yds. Lower Apartment	2,564	15	10	855
404 - Tile 15 Sq. Yds. Lower Apartment	1,890	20	12	756
420 - Tile 800 sf Lounge Upper Level	8,480	25	4	7,123
424 - Coatings 684 sf Lounge Lower Level- Stamped Concrete	4,412	15	5	2,941
630 - Vinyl 140 Sq. Yds. Game Room	8,138	15	3	6,511
670 - Vinyl 61 Sq. Yds. Upper Apartment	3,546	18	8	1,970
674 - Vinyl 93 Sq. Yds. Upper Apartment	5,568	20	17	835
920 - Coatings 3,500 sf Pavilion Floor	20,405	17	13	4,801
27000 - Appliances				
220 - 4-Burner Stove & Oven Upper Apartment	557	20	17	84
222 - Refrigerator Upper Apartment	1,134	15	9	453
224 - Refrigerator Lounge	974	15	15	61
240 - Dishwasher Upper Apartment	834	17	1	785

SUPPLEMENTARY INFORMATION ON FUTURE MAJOR REPAIRS AND REPLACEMENTS JUNE 30, 2023 (UNAUDITED)

Name	Recover Company	Current Repl. Cost	Useful Life	Remaining Life	2022/2023 Fully Funded Balance
2000 - Appliances 200 - Refigerator 1,113 20 1 1,058 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,039 1,0	·	Repl. Cost	Life	Life	Dalarice
260 - Refrigerator 1,113 20 1 1,058 Lower Apartment 1,113 15 1 1,039 132 - Washer 1,045 15 1 717 132 - Dryer 768 15 1 717 134 - Washer 1,045 10 5 522 134 - Varyer 1,045 10 5 522 134 - Dryer 1,045 10 5 522 136 - Dishwasher 1,045 10 5 522 136 - Dishwasher 1,045 10 5 522 136 - Dishwasher 1,045 10 5 522 136 - Lower Apartment 1,045 10 5 522 136 - Lower Apartment 1,045 10 5 522 136 - Aghartent 1,045 10 5 522 137 - Refrigerator: Commercial: Large 1,043 20 9 2,273 137 - Refrigerator: Commercial: Large 1,133 20 9 2,273 136 - Refrigerator: Commercial: Large 1,133 20 9 2,273 137 - Refrigerator: Commercial: Large 1,133 20 9 2,273 138 - Refrigerator: Commercial: Large 1,133 20 9 2,273 137 - Refrigerator: Commercial: Large 1,133 20 9 2,273 138 - Refrigerator: Commercial: Large 1,133 20 9 2,273 137 - Refrigerator: Commercial: Large 1,133 20 9 2,273 138 - Refrigerator: Commercial: Large 1,148 1,148 138 - Refrigerator: Commercial: Large 1,148 1,148 139 - Refrigerator: Commercial: Large 1,148 140 - Refrigerator: Commercial: Lar					
322 - Washer 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,000 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009 1,009	* *	1,113	20	1	1,058
Lower Apartment 322 - Dyrer 1,045 10 5 522		1 112	15		1.020
Lower Apartment 340 - Washer Kitchen Area- Housekeeping Washer Kitchen Area- Housekeeping Dryer 1,045 10 5 522 344 - Dyrer Kitchen Area- Housekeeping Dryer 360 - Dishwasher Lower Apartment 460 - 4-Burner Stove & Oven Lower Apartment 460 - 4-Burner Stove & Oven Lower Apartment 540 - Refrigerator: Commercial: Large Kitchen 640 - Freezer: Large Kitchen 640 - Freezer: Large Kitchen 740 - Stove / Oven: Commercial grade 6-burner Kitchen 910 - Ice Machine Lounge Sub-total Hacienda Interior 294,478		1,113	15	1	1,039
340 - Washer 1,045 10 5 522		768	15	1	717
344 - Dryer 1,045 10 5 522	340 - Washer	1,045	10	5	522
360 - Dishwasher Lower Apartment Lower Apartment 460 - 4-Burner Stove & Oven 557 20 17 84	344 - Dryer	1,045	10	5	522
450 - 4-Burner Stove & Oven 557 20 17 84	360 - Dishwasher	848	17	1	798
S40 - Refrigerator: Commercial: Large Kitchen	460 - 4-Burner Stove & Oven	557	20	17	84
640 - Freezer: Large Kitchen 529 15 8 247	540 - Refrigerator: Commercial: Large	4,133	20	9	2,273
740 - Stove / Oven: Commercial grade 6-burner 6,670 25 18 1,868 Kitchen 1910 - Ice Machine 294,478 20 20 224 20 20 224 20 20	640 - Freezer: Large	529	15	8	247
910 - Ice Machine Lounge Sub-total Hacienda Interior 294,478 Sub-total Hacienda Interior 294,478 Sub-total Hacienda Interior 294,478 200003 - Common Area 01000 - Paving 110 - Asphalt: Sealing 2,768 sf Sport Court 210 - Asphalt: Ongoing Repairs 2,768 sf Sport Court 310 - Asphalt: Overlay 2,768 sf Sport Court 310 - Asphalt: Overlay 2,768 sf Sport Court Sub-total Common Area 7,548 1 283 2,768 sf Sport Court Sub-total Common Area 7,548 4,824 00004 - Hacienda Exterior 02000 - Concrete 220 - Walkways 4,550 sf Hacienda (2%) 400 - Pool Deck 8,650 sf Pool Area Concrete (2%) 03000 - Painting: Exterior 100 - Surface Restoration 995 sf Trellises 04000 - Structural Repairs 300 - Trellis 300 - Trellis 300 - Tellis 370 sf Upper Apartment 04500 - Decking/Balconies 190 - TBA 3360 sf Upper Apartment Balcony Membranes 200 - TBA 3360 sf Upper Apartment Bedrooms Balcony 210 - TBA 3360 sf Upper Apartment Bedrooms Balcony 210 - TBA 335 Squares- Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavillion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523	740 - Stove / Oven: Commercial grade 6-burner	6,670	25	18	1,868
Sub-total Hacienda Interior 294,478 134,853	910 - Ice Machine	4,700	20	20	224
100003 - Common Area 10000 - Paving 110 - Asphalt: Sealing 747 8 1 654 2,768 sf Sport Court 210 - Asphalt: Ongoing Repairs 324 8 1 283 2,768 sf Sport Court (3%) 310 - Asphalt: Overlay 6,477 25 10 3,886 2,768 sf Sport Court 250 - Court 250		294,478			134,853
110 - Asphalt: Sealing	00003 - Common Area	.,			
2,768 sf Sport Court 210 - Asphalt: Ongoing Repairs 2,768 sf Sport Court (3%) 310 - Asphalt: Overlay 2,768 sf Sport Court Sub-total Common Area 6,477 25 10 3,886 2,768 sf Sport Court Sub-total Common Area 7,548 4,824 00004 - Hacienda Exterior 02000 - Concrete 220 - Walkways 4,550 sf Hacienda (2%) 400 - Pool Deck 8,650 sf Pool Area Concrete (2%) 03000 - Painting: Exterior 100 - Surface Restoration 9,700 sf Hacienda 110 - Surface Restoration 9,700 sf Hacienda 110 - Surface Restoration 995 sf Trellises 04000 - Structural Repairs 300 - Trellis 370 sf Upper Apartment 04500 - Decking/Balconies 190 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 179 sf Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523					
210 - Asphalt: Ongoing Repairs		747	8	1	654
310 - Asphalt: Overlay 2,768 sf Sport Court Sub-total Common Area 7,548	210 - Asphalt: Ongoing Repairs	324	8	1	283
00004 - Hacienda Exterior 02000 - Concrete 220 - Walkways	310 - Asphalt: Overlay	6,477	25	10	3,886
1,630	Sub-total Common Area	7,548			4,824
220 - Walkways					
4,550 sf Hacienda (2%) 400 - Pool Deck 8,650 sf Pool Area Concrete (2%) 03000 - Painting: Exterior 100 - Surface Restoration 9,700 sf Hacienda 110 - Surface Restoration 995 sf Trellises 04000 - Structural Repairs 300 - Trellis 370 sf Upper Apartment 04500 - Decking/Balconies 190 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 179 sf Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 12 32,941 22,941 22,941 23,942 24,500 15 15 1,531 3,912 2,941 2,942 24,500 25 1 2,842 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,942 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941 2,941		1.620			407
8,650 sf Pool Area Concrete (2%) 03000 - Painting: Exterior 100 - Surface Restoration 9,700 sf Hacienda 110 - Surface Restoration 3,343 8 5 1,254 995 sf Trellises 04000 - Structural Repairs 300 - Trellis 2,583 20 12 1,033 370 sf Upper Apartment 04500 - Decking/ Balconies 190 - TBA 4,177 25 19 1,003 539 sf [2] Upper Apartment Balcony Membranes 200 - TBA 536 sf Upper Apartment Bedrooms Balcony 210 - TBA 866 10 4 1,045 360 sf Upper Apartment Living Room Balcony 210 - TBA 250		1,630	8	6	407
100 - Surface Restoration 9,700 sf Hacienda 110 - Surface Restoration 9,700 sf Hacienda 110 - Surface Restoration 995 sf Trellises 04000 - Structural Repairs 300 - Trellis 2,583 20 12 1,033 370 sf Upper Apartment 04500 - Decking/Balconies 190 - TBA 4,177 25 19 1,003 539 sf [2] Upper Apartment Balcony Membranes 200 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 866 10 4 1,045 360 sf Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523	8,650 sf Pool Area Concrete (2%)	4,470	8	1	3,912
9,700 sf Hacienda 110 - Surface Restoration 995 sf Trellises 04000 - Structural Repairs 300 - Trellis 370 sf Upper Apartment 04500 - Decking/Balconies 190 - TBA 539 sf [2] Upper Apartment Balcony Membranes 200 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 200 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 179 sf Upper Apartment Living Room Balcony 210 - TBA 279 sf Upper Apartment Living Room Balcony 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523	_	25.026	12	1	22 941
995 sf Trellises 04000 - Structural Repairs 300 - Trellis 370 sf Upper Apartment 04500 - Decking / Balconies 190 - TBA 539 sf [2] Upper Apartment Balcony Membranes 200 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 179 sf Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523	9,700 sf Hacienda			-	
300 - Trellis	995 sf Trellises	3,343	0	5	1,254
370 sf Upper Apartment 04500 - Decking / Balconies 190 - TBA 539 sf [2] Upper Apartment Balcony Membranes 200 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 1742 10 4 1,045 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 179 sf Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523		2 583	20	12	1 033
190 - TBA	370 sf Upper Apartment	2,303	20	12	1,055
539 sf [2] Upper Apartment Balcony Membranes 200 - TBA 360 sf Upper Apartment Bedrooms Balcony 210 - TBA 179 sf Upper Apartment Living Room Balcony 25000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523		4 177	25	10	1 002
360 sf Upper Apartment Bedrooms Balcony 210 - TBA 179 sf Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523		4,1//	25	19	1,003
179 sf Upper Apartment Living Room Balcony 05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523		1,742	10	4	1,045
05000 - Roofing 200 - Low Slope: BUR 35 Squares- Upper Apartment & Pavilion 24,500 15 15 1,531 410 - Pitched: Dimensional Composition 6 Squares- Lounge & Kitchen- Access Walkways 2,960 25 1 2,842 670 - Pitched: Tile 111,168 30 8 81,523		866	10	4	520
35 Squares- Upper Apartment & Pavilion 410 - Pitched: Dimensional Composition 2,960 25 1 2,842 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523					
410 - Pitched: Dimensional Composition 2,960 25 1 2,842 6 Squares- Lounge & Kitchen- Access Walkways 670 - Pitched: Tile 111,168 30 8 81,523		24,500	15	15	1,531
670 - Pitched: Tile 111,168 30 8 81,523	410 - Pitched: Dimensional Composition	2,960	25	1	2,842
	670 - Pitched: Tile	111,168	30	8	81,523

SUPPLEMENTARY INFORMATION ON FUTURE MAJOR REPAIRS AND REPLACEMENTS JUNE 30, 2023 (UNAUDITED)

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2022/2023 Fully Funded Balance
00004 - Hacienda Exterior				
05000 - Roofing 700 - Gutters / Downspouts 703 If Hacienda	7,269	30	3	6,542
19000 - Fencing 300 - Wood 25 If Garbage Enclosure	835	15	8	390
390 - Vinyl	4,444	20	9	2,444
215 lf Hacienda Rear 394 - Vinyl	2,255	20	15	564
90 If Front of Pavilion 20000 - Lighting				
100 - Exterior: Misc. Fixtures 48 Various Lighting Fixtures (40%)	7,439	15	2	6,447
24600 - Safety / Access	6.044	4.0	_	2.470
520 - Card Readers Hacienda- Key Fob Entry	6,941	10	5	3,470
700 - Security System Hacienda	3,744	6	1	3,120
704 - Security System Hacienda Add'l Security Cameras	17,346	6	5	2,891
25000 - Flooring 400 - Tile 3,534 sf Courtyard & Entry (5%)	1,827	5	1	1,462
26000 - Outdoor Equipment				
350 - Furniture 36 Hacienda Patio Chairs	4,766	18	7	2,912
354 - Furniture 36 Tables and Umbrellas	4,766	18	7	2,912
Sub-total Hacienda Exterior	244,097			151,165
00012 - Hacienda Parking				
01000 - Paving 100 - Asphalt: Sealing	0.277	3	3	2 210
46,384 sf Parking & Rear Access Road	9,277			2,319
200 - Asphalt: Ongoing Repairs 46,384 sf Parking & Rear Access Road (2%)	2,435	3	3	609
300 - Asphalt: Overlay w/ Interlayer 46,384 sf Parking & Rear Access Road	108,539	25	16	39,074
02000 - Concrete 210 - Curbs & Gutters	2,397	10	2	1,918
2,900 If Parking Lot (2%)	2,397	10	2	1,510
03000 - Painting: Exterior 104 - Masonry Walls	1 050	12	1	970
540 If Hacienda Perimeter Stucco Walls	1,058	12	1	970
19000 - Fencing 540 - Gates	5,838	30	6	4,670
2 Entrance Gates	3,030	30	O	4,070
20000 - Lighting 540 - Parking Lot 14 Hacienda Parking Lot Lights	21,697	30	6	17,358
Sub-total Hacienda Parking	151,241			66,918
00028 - Prado Park				
01000 - Paving			_	
900 - Gravel 40 Cu. Yds. Access Road Replenish 18500 - Lakes / Ponds	4,664	8	7	583
990 - Miscellaneous 5 Dams/Spillways Cleaning (20%)	5,433	5	3	2,173
19000 - Fencing 100 - Chain Link: 4' 184 lf Outfield Fence	3,089	30	15	1,545

SUPPLEMENTARY INFORMATION ON FUTURE MAJOR REPAIRS AND REPLACEMENTS JUNE 30, 2023 (UNAUDITED)

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2022/2023 Fully Funded Balance
00028 - Prado Park				
26000 - Outdoor Equipment				
100 - Tot Lot: Play Equipment Play Equipment	27,540	20	19	1,377
108 - Miscellaneous Portable Toilet	3,500	15	15	219
901 - Miscellaneous Gregoris Park- Portable Toilet	1,845	15	6	1,107
Sub-total Prado Park	46,071			7,003
00029 - Pool				
04000 - Structural Repairs				
304 - Trellis 550 sf Pool Trellis	15,268	20	15	3,817
310 - Trellis 450 sf Pool Shade Structure	11,916	20	4	9,533
05000 - Roofing				
680 - Pitched: Dimensional Composition Pool Equipment Structure	876	25	11	490
08000 - Rehab			_	
210 - Bathrooms 2 Pool Bathrooms	47,972	20	5	35,979
12000 - Pool	22.006		_	0.004
110 - Resurface 148 If Pool	23,986	12	7	9,994
700 - Equipment: Replacement Pool (50%)	2,434	5	5	406
930 - Furniture: Misc Pool (33%)	2,226	3	2	742
990 - Miscellaneous 4 Pool Area Shade Structures	2,847	20	10	1,424
994 - Miscellaneous 4 Pool Area Shade Structures- 2022/2023	2,847	20	20	136
19000 - Fencing				
200 - Gates 6 Pool Area Gates	2,906	30	11	1,840
26000 - Outdoor Equipment				
104 - Tot Lot: Play Equipment Pool Area Lawn	15,558	15	8	7,260
200 - Pedestal Grill BBQ 3 Pool Area	1,356	12	5	791
280 - Picnic Tables 2 Pool	1,808	20	4	1,446
870 - Miscellaneous Soda Machine	2,173	10	8	435
910 - Miscellaneous Courtyard Fountain	1,324	30	11	838
Sub-total Pool	135,497			75,131
00032 - Hacienda Support				
08000 - Rehab				
104 - General Tuff Shed	3,339	20	2	3,005
180 - Doors Pavilion Double Doors	3,710	10	9	371
19000 - Fencing				
110 - Chain Link: 6' 1,606 If Perimeter Areas	35,782	30	1	34,589
23000 - Mechanical Equipment				
860 - Septic System Repairs/Maintenance	3,406	6	5	568

SUPPLEMENTARY INFORMATION ON FUTURE MAJOR REPAIRS AND REPLACEMENTS JUNE 30, 2023 (UNAUDITED)

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2022/2023 Fully Funded Balance
00032 - Hacienda Support				
26000 - Outdoor Equipment				
840 - Shade Structure	580	10	9	58
White Canopy 890 - Miscellaneous	1,808	20	4	1,446
BBQ Trailer	1,000	20	7	1,440
28000 - Water System				
100 - Distribution Line Repl. Well-Hacienda Main Water Supply	1,542	20	17	231
130 - Backflow Valves Pump House Backflow	2,183	20	10	1,091
990 - Miscellaneous Pump House- Ongoing Repairs	4,900	6	3	2,450
994 - Miscellaneous Pumphouse- Major Repairs/Replacement	20,881	14	11	4,475
30000 - Miscellaneous				
810 - Maintenance Equipment Riding Lawn Mower	3,100	15	3	2,480
812 - Tractor Massey Ferguson Tractor	42,393	20	11	19,077
820 - Vehicle Kawasaki Mule	6,519	15	13	869
Sub-total Hacienda Support	130,142			70,710
00036 - Barn				
04000 - Structural Repairs				
910 - Building Maintenance 1,056 sf Barn Structure	22,028	30	2	20,560
30000 - Miscellaneous				
990 - Trailer Utility Trailer	1,808	20	4	1,446
Sub-total Barn	23,836			22,006
				[A]
Totals	1,032,910			532,609
				[EndBal]
				[A]
Percent Funded				123%

The Association has conducted a study to estimate the useful and remaining lives and current replacement costs of common property major components. Funding requirements consider an estimated **before-tax interest rate** of **2-1/2%** on replacement fund cash balances and an annual **inflation rate** of **1-1/2%** on major component replacement costs. The replacement fund **cash** and investment balances at June 30, 2023 totaled **\$650,607**. The estimated **liability** for major repairs and replacements at this date totaled approximately **\$533,000**. The portion of **2024** regular **assessments** budgeted to be allocated to the replacement fund totals **\$35,000**.